

Work Order ID 77326

December-02-11 1:59:06 PM

77326

Page 1

Item ID: D2966-1-BENT

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Skidtube Assembly 105

Start Date: 02/12/2011 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 07/12/2011 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals: Process Plan: MLJ Date: 11/12/02 Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2966	Rev A								
120	BENDING MACHINE - SKIDTUBES	0.00							
120									
CNC Bend 1	Memo	0.00							
CNC Delta 100 Bender	Bend tube as per program BO105 on CNC Bender and Dwg D2966. Bend folio #1 use bending aid DT9631								
150	QC5- Inspect part completeness to step on W/O	0.00							
150									
QC	Memo	0.00							
Quality Control									
300	Identify as per dwg & Stock Location: <u>LG</u>	0.00							
300									
Packaging	Packaging								
Packaging	Memo	0.00							

DP

11-12-7

1 0 BE11-12-12

1 0 SAD11-12-12

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 77326***77326***

Page 2

December-02-11 1:59:06 PM

Item ID: D2966-1-BENT

Accept

N900040100Setup Start ***NS1***

Revision ID:

Item Name: Skidtube Assembly 105

Stop ***NS2***

Start Date: 02/12/2011 Start Qty: 1.00

1

Cust Item ID:

Required Date: 07/12/2011 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
310	QC21- Final Inspection - Work Order Release	0.00							
310									
QC	Memo	0.00							
Quality Control									

mr
11-12-12

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

December-02-11 1:59:10 PM

Page 1

Work Order ID: 77326

77326

Parent Item: D2966-1-BENT

D2966-1-BFNT

Parent Item Name: Skidtube Assembly 105

Start Date: 02/12/2011

Required Date: 07/12/2011

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP rev A 10.09.17 New issue EC verified by:DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2962-125 *D2962-125* Outer Tube Extrusion		Manufactured	No				Each	23.0000		1			
									**	DP 11-12-7			

Location

Loc Qty

Loc Code

HALL

23

17532

23

①

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN <i>RF</i>	DRAWN BY <i>RF</i>	DART AEROSPACE USA, INC. BELLEVUE, WA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D2966	REV. A SHEET 1 OF 2
DATE 00.03.08		TITLE BO 105 SKIDTUBE ASSEMBLY SCALE NTS	
A	00.03.08	NEW ISSUE	

RELEASED
00.05.11 *[Signature]*

Qty	Part Number	Description
X	D2966-041	SKIDTUBE ASSEMBLY
1	D2962-125	EXTRUSION
1	D2964	CAP
1	D2965	CAP
1	D2970-1	WEARPLATE
1	D2970-3	WEARPLATE
1	D2971	CROSS BOLT SPACER
7	D2973	CROSS BOLT SPACER
1	D2976	WEB
36	ALS7-1032-130 or ALS4-1032-130 or AKS7-1032-130 or AKS4-1032-130	INSERT
28	AN960JD10L	WASHER
26	MS27039-1-08	SCREW
2	MS27039-1-09	SCREW
1	D3176-1	BUSHING
1	D3176-3	NUT

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 77326
M.C.J.
11/12/02



GENERAL NOTES:

- 1) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 2) WELDING TO BE DONE PER DART QSI 004.
- 3) INSERT D2976 WEB TO LOCATION SHOWN OFF AFT END OF SKIDTUBE AND BOND WEB INTO OUTER TUBE WITH NON-STRUCTURAL SIKAFLEX-241/-291 ADHESIVE PER DART QSI 015 AFTER BENDING.
- 4) USE DART DRILL TEMPLATE DT8451 TO LOCATE AND DRILL Ø0.297 HOLES FOR WEARSHOE INSERTS. INSTALL ALS7-1032-130 PER SECTION B-B (34 PLACES) AFTER FINISH. SEAL WEARPLATE SCREWS WITH SIKAFLEX-241/-291.
- 5) DO NOT INSTALL MS27039-1-08 SCREWS AND AN960JD10L WASHERS IN THESE LOCATIONS.
- 6) INSTALL ALS7-1032-130 INSERT, MS27039-1-08 SCREW, AND AN960JD10L WASHER IN 2 PLACES THIS LOCATION BEFORE POWDER COATING.
- 7) FINISH:

ACID ETCH, ALODINE PER DART QSI 005 4.1 PRIOR TO INSERTING D2976 WEB
POWDER COAT ASSEMBLY GLOSS WHITE (REF 4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT AS INDICATED TO 1.00 ABOVE CENTER LINE PER DART
QSI 005 4.4 (OPTIONAL) BLACK SANDTEX (REF 4.3.5.7)



[Signature] 01.01.24
CP 01.01.30

A2	02.10.30	ADD D3176-1/-3	<i>[Signature]</i> UP
A1	01.01.24	CHANGE COLOR TO BLACK SANDTEX	<i>[Signature]</i> UP

Copyright © 2000 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector



Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____


NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries


77326

DETAIL A
SCALE 1:3SECTION B-B
SCALE 1:6


- AFTER BENDING AND DRILLING ASSEMBLY
PERFORM THE FOLLOWING FOR $\phi 0.750$ HOLES ONLY:
1. CHAMFER HOLE $0.030 \times 45^\circ$
 2. INSERT D2973 SPACER (7 PLACES)
 3. WELD INTO PLACE AND GRIND FLUSH
 4. PASS $\phi 0.630$ DRILL TO REMOVE SPILL OVER

SECTION C-C
SCALE 1:6


- PERFORM THE FOLLOWING FOR $\phi 0.625$ HOLES ONLY:
5. CHAMFER HOLE $0.030 \times 45^\circ$
 6. INSERT D2971 SPACER
 7. WELD INTO PLACE AND GRIND FLUSH
 8. PASS $\phi 0.484$ DRILL TO REMOVE SPILL OVER

DETAIL D
SCALE 1:4


D2966-1 BENDING/CUTTING DETAIL



D2966-1 DRILLING DETAIL



D2966-041 ASSEMBLY DETAIL



COPYRIGHT © 2000 BY DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL
AND IS SUPPLIED ON THE EXPRESS CONDITION
THAT IT IS NOT TO BE USED FOR ANY PURPOSE
OR COPIED OR COMMUNICATED TO ANY OTHER
PERSON WITHOUT WRITTEN PERMISSION FROM
DART AEROSPACE USA, INC.

DESIGN
RF

CHECKED
RF

DATE
00.03.08

DRAWN BY
RF

APPROVED
RF

DART DART AEROSPACE USA, INC.
BELLUVE, WADRAWING NO.
D2966TITLE
BO 105 SKIDTUBE ASSEMBLYREV. A
SHEET 2 OF 2SCALE
1:20RELEASED
05-05-11

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries